


# Relation between inundation depth and damage of structures due to the 2011's Tsunami





The report by city bureau of MLIT



# Relation between inundation depth and damage of structures

## Kind of structures

The report by city bureau of MLIT



- 凡例
- 全壊 (流失)
  - 全壊
  - 全壊 (1階天井以上浸水)
  - 大規模半壊
  - 半壊 (床上浸水)
  - 一部損壊 (床下浸水)
  - 被災なし

<http://fukkou.csis.u-tokyo.ac.jp/>

ID: taro.arikawa

Password: Q453WoV0